FIELD DATA COLLECTION FORM FOR INTRASTATE INSPECTORS

Page 1 of 3

NOTES-FIELD INSPECTION

Company: Puget Sound Energy Date(s): July 20 – 23, 2015

Unit: King County West

Field Readings									
Line & Location	Line		CP Volts		Rectifier		Pressures (in psig)		Remarks
	Size	In.	P/S	Casing	Volts	Amps	Set	Actual	
RS-2561 Beacon Coal Mine Rd and 57th RS-2748 5900 West Marginal Way							LU 42 Relief 47 140 upstream Relief 37 Run 2 LU 32	40.6 LU Relief 47.1 141 upstream Relief 37 Run 2 32	231.6 psig upstream 45 psig MAOP downstream Direct operated relief 150 psig MAOP upstream 60 psig MAOP downstream
RS-2790 SW Highland and SW Holden							Run 1 LU SP @55.8	140.5 inlet Run 1 flowing at 53.8 Run 1 LU actual as found and left @ 57	150 psig MAOP upstream 60 psig MAOP downstream
RS-2772 3800 Gilman Ave West							Run 1 LU SP 42	142 inlet 39 downstream 41.28 LU as found	150 psig MAOP upstream 45 psig MAOP downstream

FIELD DATA COLLECTION FORM FOR INTRASTATE INSPECTORS

Page 2 of 3

						Page 2 of 3
RS-2721 5 th Ave and NE 88 th				Relief 47	Relief 48.5 Reseated at 44.8	45 psig MAOP downstream **Only checked relief due to operator OT**
PS-0405 765 202st	- 2306mV CSE (on) -868mV CSE	24	2.16			
	(off)					
TS-054284 20308 Whitman Ave NE	- 1512mV CSE galvanic					
TS-075784 7708 234 th SW	-955mV CSE galvanic					
PS-0399 Broadway Ave and Columbia	- 1284mV CSE (on)	16.75	2.36 A			
	1000mV CSE (off)					
Belmont and Bellevue Pl	-510mV (on)					IC system - ***Shorted Area of Concern in inspection letter***
Bridge Inspection 8 th Ave and NW 136 th St						

FIELD DATA COLLECTION FORM FOR INTRASTATE INSPECTORS

Page **3** of **3**

	 	 	Page 3 of 3
Bridge Inspection			
10 Ave NW and			
NW Innis Arden			
Way			
Slide Patrol 2900-			
3000 Block NE			
178th			
Bridge Inspection			"Utilidor" at this location
I-5 and 145 th St			
Bridge Inspection			
Interurban and			
42 nd			
Bridge Inspection			
Interurban and			
Fort Dent			
Slide Patrol			
Sunwood and			
62nd			
Odorant Sniff Test			4-14% LEL is what PSE
Readings			uses8 Readings are the
			limit for 1/5 th of the LEL
5 th and Roy			.25
165 th and Dayton			.21
123 rd and			.22
Sandpoint Way			
N 89 th and			.24
Fremont			
Valve accessibility			OK
verificationVA-			
00271 South 124 th			
and 51 PL S			